

show running

```
Current configuration : 1464 bytes
version 12.4
service timestamps debug datetime msec
service timestamps log datetime msec
no service password-encryption
hostname FRAD_CIX
boot-start-marker
boot-end-marker
logging message-counter syslog
no logging buffered
no logging console
no logging monitor
no aaa new-model
dot11 syslog
ip source-route
ip cef
no ipv6 cef
multilink bundle-name authenticated
voice-card 0
no dspfarm
username cisco privilege 15 secret 5 $1$EJga$0HI8Ah/9bb/V3BWKUXkN81
log config
hidekeys
interface FastEthernet0/0
no ip address
shutdown
duplex auto
speed auto
interface FastEthernet0/1
description to_FW
ip address 3.3.3.5 255.255.255.252
duplex auto
speed auto
mpls ip
interface Serial0/2/0
description to_FR
ip address 128.0.0.3 255.255.255.0
encapsulation frame-relay
ip ospf network point-to-multipoint non-broadcast
no fair-queue
clock rate 2000000
interface Serial0/2/1
no ip address
shutdown
clock rate 2000000
router ospf 1
router-id 3.3.3.3
log-adjacency-changes
passive-interface FastEthernet0/1
network 3.3.3.5 0.0.0.0 area 1
ip forward-protocol nd
no ip http server
no ip http secure-server
control-plane
```



line con 0
logging synchronous
login local
line aux 0
line vty 0 4
logging synchronous
login local
line vty 5 15
logging synchronous
login local

scheduler allocate 20000 1000 end



show version

Cisco IOS Software, 2800 Software (C2800NM-ADVENTERPRISEK9-M), Version 12.4(20)T1, RELEASE SOFTWARE (fc3)

Technical Support: http://www.cisco.com/techsupport Copyright (c) 1986-2008 by Cisco Systems, Inc. Compiled Wed 24-Sep-08 14:36 by prod_rel_team

ROM: System Bootstrap, Version 12.3(8r)T7, RELEASE SOFTWARE (fc1)

FRAD_CIX uptime is 1 week, 3 days, 39 minutes System returned to ROM by reload at 22:45:58 UTC Wed Dec 27 1933 System image file is "flash:c2800nm-adventerprisek9-mz.124-20.T1.bin"

This product contains cryptographic features and is subject to United States and local country laws governing import, export, transfer and use. Delivery of Cisco cryptographic products does not imply third-party authority to import, export, distribute or use encryption. Importers, exporters, distributors and users are responsible for compliance with U.S. and local country laws. By using this product you agree to comply with applicable laws and regulations. If you are unable to comply with U.S. and local laws, return this product immediately.

A summary of U.S. laws governing Cisco cryptographic products may be found at: http://www.cisco.com/wwl/export/crypto/tool/stqrg.html

If you require further assistance please contact us by sending email to export@cisco.com.

Cisco 2811 (revision 53.51) with 249856K/12288K bytes of memory. Processor board ID FHK0905F08W 2 FastEthernet interfaces 2 Serial(sync/async) interfaces 1 Virtual Private Network (VPN) Module DRAM configuration is 64 bits wide with parity enabled. 239K bytes of non-volatile configuration memory. 62720K bytes of ATA CompactFlash (Read/Write)

Configuration register is 0x2102