

show running-config

```
Current configuration: 988 bytes
version 12.4
service timestamps debug datetime msec
service timestamps log datetime msec
no service password-encryption
hostname Router
boot-start-marker
boot-end-marker
logging message-counter syslog
no aaa new-model
dot11 syslog
ip source-route
ip cef
no ipv6 cef
multilink bundle-name authenticated
voice-card 0
archive
log config
hidekeys
interface FastEthernet0/0
ip address 192.168.1.10 255.255.255.0
duplex auto
speed auto
interface FastEthernet0/1
no ip address
shutdown
duplex auto
speed auto
interface Serial0/2/0
ip address 10.7.8.9 255.255.255.0
no fair-queue
clock rate 2000000
interface Serial0/2/1
ip address 10.5.100.78 255.255.255.252
clock rate 2000000
ip forward-protocol nd
no ip http server
no ip http secure-server
control-plane
line con 0
line aux 0
line vty 0 4
login
scheduler allocate 20000 1000
end
```



show ip int brief

Interface IP-Address OK? Method Status Protocol FastEthernet0/0 192.168.1.10 YES manual up up FastEthernet0/1 unassigned YES unset administratively down down Serial0/2/0 10.7.8.9 YES manual down down Serial0/2/1 10.5.100.78 YES manual down down



show version

Cisco IOS Software, 2800 Software (C2800NM-ADVENTERPRISEK9-M), Version 12.4(24)T2, RELEASE SOFTWARE (fc2) Technical Support: http://www.cisco.com/techsupport Copyright (c) 1986-2009 by Cisco Systems, Inc. Compiled Mon 19-Oct-09 17:38 by prod_rel_team ROM: System Bootstrap, Version 12.4(13r)T11, RELEASE SOFTWARE (fc1) Router uptime is 1 week, 2 days, 23 hours, 43 minutes System returned to ROM by reload at 12:59:28 UTC Fri Dec 23 2016 System image file is "flash:c2800nm-adventerprisek9-mz.124-24.T2.bin" This product contains cryptographic features and is subject to United States and local country laws governing import, export, transfer and use. Delivery of Cisco cryptographic products does not imply third-party authority to import, export, distribute or use encryption. Importers, exporters, distributors and users are responsible for compliance with ${\tt U.S.}$ and local country laws. By using this product you agree to comply with applicable laws and regulations. If you are unable to comply with ${\tt U.S.}$ and local laws, return this product immediately. A summary of U.S. laws governing Cisco cryptographic products may be found at: http://www.cisco.com/wwl/export/crypto/tool/stqrg.html If you require further assistance please contact us by sending email to export@cisco.com. Cisco 2811 (revision 53.51) with $512000 \mbox{K}/12288 \mbox{K}$ bytes of memory. Processor board ID FCZ142270AY 2 FastEthernet interfaces 2 Serial(sync/async) interfaces 1 Virtual Private Network (VPN) Module DRAM configuration is 64 bits wide with parity enabled. 239K bytes of non-volatile configuration memory. 62720K bytes of ATA CompactFlash (Read/Write) Configuration register is 0x2102