

## sh version

Cisco IOS Software, C2600 Software (C2600-ADVIPSERVICESK9-M), Version 12.4(23), RELEASE SOFTWARE (fc1)

Technical Support: http://www.cisco.com/techsupport Copyright (c) 1986-2008 by Cisco Systems, Inc. Compiled Sat 08-Nov-08 20:53 by prod\_rel\_team

ROM: System Bootstrap, Version 12.2(7r) [cmong 7r], RELEASE SOFTWARE (fc1)

Router uptime is 1 day, 21 hours, 31 minutes System returned to ROM by power-on System image file is "flash:c2600-advipservicesk9-mz124-23.bin"

This product contains cryptographic features and is subject to United States and local country laws governing import, export, transfer and use. Delivery of Cisco cryptographic products does not imply third-party authority to import, export, distribute or use encryption. Importers, exporters, distributors and users are responsible for compliance with U.S. and local country laws. By using this product you agree to comply with applicable laws and regulations. If you are unable to comply with U.S. and local laws, return this product immediately.

A summary of U.S. laws governing Cisco cryptographic products may be found at: http://www.cisco.com/wwl/export/crypto/tool/stqrg.html

If you require further assistance please contact us by sending email to export@cisco.com.

Cisco 2621XM (MPC860P) processor (revision 1.0) with 127308K/3764K bytes of memory. Processor board ID JAD063500FG M860 processor: part number 5, mask 2

2 FastEthernet interfaces

2 Serial(sync/async) interfaces

1 ISDN Basic Rate interface

32K bytes of NVRAM.

32768K bytes of processor board System flash (Read/Write)

Configuration register is 0x2142