Registros PWM

Input/Output	Write/Read	Address
Cnt_up	R	0+00
Cnt_dn	R	0+02
Clk	R	0+04
Reset	R	0+06
O_Servo	W/R	0+08

Registros Controlador_output

Input/Output	Write/Read	Adress
Input	R	0+00
Clk	R	0+02
Reset	R	0+04
Cnt_up	W	0+06
Cnt_dn	W	0+08

Registros GPIO

Input/Output	Write/Read	Adress
Input	W	0+0000
Reset	R	0+0200
Clk	R	0+0400
O_Servo	W/R	0+0600