

INSTALLATION

Step 1: Download CAD_to_GIS.pyt

https://github.com/dacostasw/CAD-to-GIS







Download

And save in preferred Folder


Step 2: Install CAD_to_GIS.pyt in ArcGIS Toolbox




In Catalog Panel, look for “Toolboxes”.



Locate .pyt file in the folder and add to Toolbox




Click ‘OK’




‘Double-click’ to open
And ready to use

USAGE



1. Select CAD files to process and import. Could be an entire folder containing subfolders with different .dwg files.


2. Select reference layer from the working project or outside the project. The tool uses this layer to assign projection to .dwg



3. Select mode. **Check only** will verify each .dwg file and generate a report of the status. **Check and fix** is the next step, which will fix any file with unknown projection.

4. Select file type (.dwg default)

5. (Optional) Select known coordinate system for the working project, if the selected reference layer is in doubt. It will use this to double check.



6. Select "**Output options**" and "**Run**" tool. Check "Add ready drawings" if importing right away.

CAD folder containing 8 subfolders

