Reporte detallado

Información General

Archivo procesado: Reporte_Componentes_Estructurado.txt

Total de líneas analizadas: 118

Path del archivo: /var/log/memlat/failed latency test 1623900021

Resumen de ocurrencias por palabra clave

Palabra clave	Ocurrencias
WARNING	2

Detalles de coincidencias encontradas

[WARNING] WARNINGS High memory access latency was detected during the stress test, potentially impacting real-time performance. Investigation required to determine root cause. [WARNING] WARNINGS overheating detected

Ingredient Information

Campo	Valor
os_version	Ubuntu 20.04
ifwi_version	1.0.3
kernel_version	5.15.0-92-generic
bios_version	1.3.7
vm_config	H1
bmc	2.10.4

Anomalías detectadas

Average latency observed: 382ns | Max latency spike: 476ns WARNINGS High memory access latency was detected during the stress test, potentially impacting real-time performance. Investigation required to determine root cause. WARNINGS overheating detected

Métricas con Netdata

No se encontraron métricas Netdata en el archivo.