# Reporte detallado

## Resumen de ocurrencias por palabra clave

Palabra clave	Ocurrencias
WARNING	1

#### Detalles de coincidencias encontradas

[WARNING] WARNINGS High memory access latency was detected during the stress test, potentially impacting real-time performance. Investigation required to determine root cause.

### **Ingredient Information**

Campo	Valor
os_version	Ubuntu 20.04
ifwi_version	1.0.3
kernel_version	5.15.0-92-generic
bios_version	1.3.7
vm_config	H1
bmc	2.10.4

#### Anomalías detectadas

Average latency observed: 382ns | Max latency spike: 476ns WARNINGS High memory access latency was detected during the stress test, potentially impacting real-time performance. Investigation required to determine root cause.

## **Test Completion Status**

**FAILED**