Reporte detallado

Información General

Total de líneas analizadas: 197
Path del archivo: /var/log/memlat/failed_latency_test_1623900021
Program installed: DOCKER, FIREFOX
Programas abiertos: stressng

Resumen de ocurrencias por palabra clave

Palabra clave	Ocurrencias
WARNING	1

Detalles de coincidencias encontradas

[WARNING] WARNINGS High memory access latency was detected during the stress test, potentially impacting real-time performance. Investigation required to determine root cause.

Ingredient Information

Campo	Valor
os_version	Ubuntu 20.04
ifwi_version	1.0.3
kernel_version	5.15.0-92-generic
bios_version	1.3.7
vm_config	H1
bmc	2.10.4

Anomalías detectadas

Average latency observed: 382ns | Max latency spike: 476ns
WARNINGS High memory access latency was detected during the stress test, potentially impacting real-time performance. Investigation required to determine root cause.

Métricas con Netdata

Métrica	Valor
CPU	67%
RAM	65%
Disco	82% usado
Red (eth0)	Rx: 1.2 MB/s, Tx: 900 KB/s

Test Completion Status

FAILED