

SmartButler - Night Shift Operational Summary (2026-09-23)

Generated: 2026-09-23 06:45:00 | Facility: SmartButler Grand Hotel | Shift: Night

Section 1: Critical Maintenance Work Orders

MNT-7412-3 | Room 412 (VIP) | Category: HVAC | Status: WaitingParts | Priority: Urgent

Issue: HVAC cooling compressor clutch failure. Room warm at 26C. Guest VIP Dr. Ben-Ari irritated.

Assigned: David L. (Night Tech) | Notes: Fan provided. WaitingParts Chiller compressor valve.

MNT-801 | Room 205 | Category: Plumbing | Status: WaitingParts | Priority: Urgent

Issue: Pipe burst in bathroom ceiling. Flooding into corridor. Room taken out of order.

Assigned: Yossi C. | Notes: WaitingParts replacement 1/2-inch copper pipe joiner.

MNT-802 | Room 304 | Category: Electrical | Status: WaitingParts | Priority: High

Issue: Main breaker tripping repeatedly under load. Suspected coil degradation.

Assigned: Ahmed K. | Notes: WaitingParts 40A Schneider breaker module.

MNT-803 | Boiler Room | Category: Plumbing | Status: WaitingParts | Priority: Urgent

Issue: Secondary boiler circulation pump seal leaking hot water.

Assigned: David L. | Notes: WaitingParts mechanical pump seal model Grundfos B2.

Section 2: Duty Manager Incident Logbook & Compensations

LOG-501 | Room 412 | Guest: Dr. E. Ben-Ari (VIP) | Compensation: 1,200 ILS (Spa & Dinner Credits)

Incident: Third AC failure in 36 hours. Duty Manager personal intervention and executive apology.

LOG-502 | Room 205 | Guest: Mr. Sharon Cohen | Compensation: 850 ILS (Room Upgrade + Wine)

Incident: Severe ceiling leak and carpet water damage. Emergency guest relocation to Suite 601.

LOG-503 | Floor 3 | Guest: Multi-room guests | Compensation: 0 ILS

Incident: Wi-Fi gateway packet drops on floor 3 access point. Escalated to telecom provider.