

Calibration.

Sensors measure Volts - the computer interprets that information based on an equation D.D. and turbidity sensors will give different readings over time and in different environments. I We need to tell the computer Light equation to use

Calibration Curve:





- 1. Copy notes or 5 minute break
- 2. In groups of 3: Each person should calibrate BOTH SENSORS

