· Test upor sensor with: -> Omg/L brown bottle -> "Hover" bottle 8.7 mg/L - the water from creek -> cap it/fill all the way

-> take mmts as guickly
as possible -> Stir for about 10s gently -> enter data up front