## Calibration / Use.

Temperature - no calibration

- Use thermometer
- hold bottles at the edge
- take temp. ASAP

PH - no calibration

- Unsurew soaking solin cap 1st
- take multiple measurements

turbidity - calibrate to 0 NTU (openable bottle w/top water) and 100 NTU (sealed cloudy bottle) - test sample water in obenable bottle - clean bottles before putting in sensor

DD - Fill cap v/electrode filling sol'n - Calibrate to Ong/L (brown bottle) and 8.6 mg/L 5 (hover bottle) - Measure your sample

## Pros/Cons of Water Quality Index:

PRO: Dannyboy Cr: 79/100 Water Quality index for trout suitability.

Seth Slough: 87/100 "

Which creek has lower temperature?

ON: details

lose details

mainimens

of mainimens

4

Swimming WQI

0	Good (ideal)		OK		Poos	
most inp PH	•	20	4-5 8-9	10	0-4 9-14	0
2nd most temp	70-80° F	10	50-20°F	5	>100°F	0
3rd most turb.	O-100 NTU	5	100-540 NTV	3	כולא סלבל	1
desit Don	m	<u> </u>	~		~	
·						