for your projects, the force sensors must: 1. Be easily attached and removed 2. Allow you to calculate the work done to or by the sensor

acement (Of the sensor) in the same direction as mores backwards

Force on sensor Displacement aveoges