

FEM-anchor residual  $|\Delta|$  (%)

$10^0$

$10^{-1}$

$\sim 1.4\%$  (mis-attributed to  $2\pi$  bug)

$< 0.1\%$  (truncation was the cause)

—●— far-field sweep (same deck)

$\sim 5\times$

$\sim 10\times$

far-field truncation  $R_{\text{out}}/H_{\text{out}}$  (coil radii)

