

Service Hub - 2018 Alfa Romeo Stelvio 2.0T

VIN ZASFAKPN5J7B88115 | about 142,290 km | Q4 AWD, ZF 8HP | cuore, 2026-09-26

Section	Key specs (confidence)	Last known service	Open items	cuore page
Engine oil & service	0W-30 full synthetic, FCA MS-13340 (CORROB.). 5.5 qt / 5.2 L with filter (SINGLE). Filter Mopar 4892339 (not 68191349 = V6). Drain plug 20 Nm, filter cap 25 Nm (SINGLE). Shop interval 8,000 mi / 12 mo (CORROB.); FCA max 10,000 mi / 1 yr, severe duty 4,000 mi (CONFIRM.).	Oil change reset logged in MES 2026-09-15 (no odometer). Turbo replaced 2025-10-14 (overboost counter reset).	Record the oil change details in cuore (brand, filter, torques applied, condition).	/v/<VIN>/oil-change
Routine maintenance	Owner's manual (CONFIRM.): air filter 30k mi; cabin filter 20k mi / 2 yr; spark plugs 30k mi (mileage only), NGK 90219 / Mopar 68292346AA (CORROB.), 19.5 Nm (CORROB.); coolant OAT MS.90032, 8.8 L engine circuit + separate intercooler circuit; brake fluid DOT 4 MS.90039 every 2 yr; drive belt 36k mi / 4 yr; A/C R-1234yf. PCV, throttle body, boost hoses: UNKNOWN.	Oil-change reset only (MES 2026-09-15). No maintenance items recorded yet.	Record a baseline visit (what is known to be done, with odometer) so due dates can be calculated.	/v/<VIN>/maintenance
Brakes, wheels & tyres	Front rotor 330 x 28 mm new, 25.5 mm min (SINGLE); rear min UNKNOWN (read cast MIN TH). DOT 4, MS.90039, change every 2 yr (CONFIRM.). 235/60R18 or 235/55R19 (CORROB.). Lugs 121 Nm / 89 lb-ft (CORROB.). Pressures: read the door placard.	No brake/tyre record yet.	Rear pads: put the electric park brake in service mode first (MES or wiTECH).	/v/<VIN>/brakes-tires
Transmission (ZF 8HP)	ZF LifeguardFluid 8 / Mopar 68218925AA, NOT ATF+4. Level check only at 30-50 C (CONFIRM.). Pan/filter bolts 10 Nm (CONFIRM.). Drain/fill plug torques UNKNOWN. Relearn adaptations after service.	No transmission service on record.	TSB 21-035-20 TCM flash applies to this VIN: check on wiTECH.	/v/<VIN>/drivetrain/transmission
Transfer case (Q4)	Tutela, FIAT 9.55550-DA11 (CORROB.). Capacity ~0.7 L, sources conflict. Plug torques UNKNOWN. Replace oil at 80k mi / 128k km / 8 yr (CONFIRM., owner's manual).	No record.	DUE: car is past 128,000 km. Replace transfer case oil unless records show it was done.	/v/<VIN>/drivetrain/transfer_case
Differentials	Front 75W-80 GL-5 DA10, 0.5 L; rear 75W-85 DA9, 0.9-1.1 L by unit (SINGLE). Rear plugs 26 Nm (SINGLE); front plugs UNKNOWN. Which rear unit (open/LSD/eLSD) this VIN has: UNKNOWN.	No record.	-	/v/<VIN>/drivetrain/differentials
Driveline	Hub nut 52 lb-ft + 47 deg, SINGLE-USE (SINGLE). Hub mount bolts 74 lb-ft (SINGLE). Propshaft flange UNKNOWN (online 72-101 lb-ft figure is from a 1970s Alfa: do not use).	No record.	-	/v/<VIN>/drivetrain/driveline
Mounts	Engine mount bolts 22-27 Nm; dogbone 25-31 Nm, single-use (SINGLE). Strut-to-lower-arm and upper-arm torques UNKNOWN (fabricated values withdrawn in fact-check).	No record.	-	/v/<VIN>/drivetrain/mounts
EVAP & emissions	P0455, P0456, P0440 chronic. System sealed (3 smoke tests); canister, ESIM, cap, filter, purge valve all new. ECM software 52170619 / P235QB39.	Codes cleared 2026-09-25 20:27; tests not re-run yet.	Next: wiTECH flash check, then Test A (ESIM switch in wiTECH). Recalls 25V586000 (fuel pump) and 18V636000 (2.0L ECM software) to check.	/tree, /dashboard
Network / body / ADAS	BCM U1711/U1712/U1713, DASM C141C and C141B, B1176 window riser, RFHUB B1040 (likely bystander).	Chronic since 2026-06-07.	Grey-cable read of ABS/HALF; network-cascade fault tree first steps.	/v/<VIN>/tree

Confidence: CONFIRM. = manufacturer document; CORROB. = two independent sources; SINGLE = one source; UNKNOWN = use the FCA service manual (TechAuthority). Torque data fact-checked 2026-09-26. Full torque tables: 'Stelvio Torque Settings' and 'Stelvio Drivetrain Torque Settings' PDFs, and the cuore torque page.