

Dossier - 2018 Alfa Romeo Stelvio 2.0T

VIN ZASFAKPN5J7B88115 | 114,117 to 142,290 km | 37 logs 24 Sep '25 to 4 Oct | 4 ECUs | as of 2026-10-07 | Simulation logs excluded. SCAN provenance is unverifiable (no simulation marker exists in that format).

UNVERIFIED REPAIR

EVAP leak (P0455/P0440/P0456) cleared 29 Sep; monitors have not re-run. Not proof of repair.

Latest: engine session 4 Oct read clean; all-systems scan 4 Oct no faults. Both after the clear on 29 Sep (SCAN_2609291046.txt). Last session with findings: 25 Sep, P0455-00, P0440-00, P0456-00.

Actions: Verify repair (read readiness with the car connected) | EVAP fault tree | Evidence gate. Next: drive until the EVAP monitor re-runs (fuel 15-85 %, cold starts, several drives), then read readiness or re-scan. A returning code is the answer; silence right after a clear is not.

Open work (tick as you go; the cuore dossier keeps the shared tick state)

EVAP: one system fault P0440 P0455 P0456		Network: one power / bus event U0100 U0418 U0428 U1700 U1701 U1711 +6	
[] 1. Inspect the recirculation-line quick-connect	S2125000002	[] 1. Supply side first: BCM feeds, fuse F82	S1808000005
[] 2. Purge / vent valve actuation, key on engine off	MES actuators	[] 2. Connectors and grounds XY201, G003A/B	S2008000032
[] 3. Hose routing check	9100325	[] 3. Terminals	S1708000262
[] 4. Canister and ESIM check	9100471		
[] 5. Smoke test to localise	done 3x: sealed		
[] 6. Small-leak verification: wiTECH SLVT or Mode \$06	18-048-23		

Chronic codes (11) with status

Code	Description	Sys	Status	xN	Last seen	km span
P0440-00	Evaporation control valve	Engine	CLEARED, UNVERIFIED	11	29 Sep	1,717
P0456-00	Evaporation system leak	Engine	CLEARED, UNVERIFIED	7	25 Sep	28,173
P0455-00	Evaporation system leak	Engine	CLEARED, UNVERIFIED	4	25 Sep	1,717
U1713-2F	Engine control (NCM) - Signal/message erratic	Network	CLEARED, UNVERIFIED	8	28 Sep	-
B1176-97	Rear left window riser - Component or system operation obstr	Body	CLEARED, UNVERIFIED	8	29 Sep	-
U1712-2F	Brake system (NFR) - Signal/message erratic	Network	CLEARED, UNVERIFIED	6	25 Sep	-
U1711-2F	Brake system (NFR) - Signal/message erratic	Network	CLEARED, UNVERIFIED	6	25 Sep	-
C141C-86	Private CAN between HALF and DASM - Signal/message invalid	Chassis	CLEARED, UNVERIFIED	6	25 Sep	-
U0100-87	No communication with engine control unit (ECU) - Missing me	Network	CLEARED, UNVERIFIED	5	28 Sep	-
C141B-97	Camera blinded/obstructed/blocked - Component or system oper	Chassis	CLEARED, UNVERIFIED	5	28 Sep	-
B1040-64	Communication with Body Computer (BCM/NBC) - Signal/message	Body	CLEARED, UNVERIFIED	4	28 Sep	-

Seen once (17, stale): P1189-00 (24 Sep '25), P00F5-00 (24 Sep '25), P0098-00 (24 Sep '25), P105E-00 (24 Sep '25), U1701-86 (7 Jun), B1029-64 (27 Aug), B102E-64 (27 Aug), U1716-2F (27 Aug), U2054-87 (27 Aug), C1403-86 (27 Aug), C1431-86 (27 Aug), C104B-92 (4 Sep), U1700-87 (4 Sep), U1960-83 (4 Sep), U0428-86 (4 Sep), U0418-86 (4 Sep), U1765-86 (15 Sep)

Bulletins

Bulletin	What it says	Codes
18-030-17 REV. B	PCM flash family fixed-DTC list includes the EVAP codes	P0440 P0455 P0456
S2125000002	EVAP leak codes -- check the recirculation-line quick-connect first	P0455 P0456
18-048-23	EVAP small-leak verification requires wiTECH SLVT	P0456

Blind spots: what the logs cannot answer

Question	Action
Has each emissions monitor RUN since the last clear?	obd2.read_readiness (car connected, ELM327 on COM3)
Is a permanent (Mode \$0A) DTC standing?	obd2.read_permanent_dtcs (car connected)
What did the on-board leak test actually MEASURE?	pending build; reachable today via obd2.send_raw
Is the ECM on the latest calibration?	dealer wiTECH ECU flash check on the VIN; the exact request is in EVAP fault tree step E8
Will the EVAP monitor run on the next drive?	check fuel level before the verification drive

Already attempted

Operation	Outcome	xN	First	Last
Electronic thermostat	Failed To Execute	5	24 Sep '25	15 Sep
Fan 1st speed	Failed To Execute	1	27 Aug	27 Aug
Evaporation control valve	Completed	18	24 Sep '25	15 Sep
EGR solenoid valve	Completed	2	14 Oct '25	15 Sep
Oil change	Completed	2	15 Sep	15 Sep
Wastegate solenoid valve	Completed	2	24 Sep '25	14 Oct '25
Turbo vacuum valve	Completed	2	24 Sep '25	14 Oct '25
Overboost counter reset	Completed	1	14 Oct '25	14 Oct '25
Replacement of turbocharger	Completed	1	14 Oct '25	14 Oct '25

MES actuator tests on the IAW 10JA need key-on engine-off: 'Engine running' is an interlock, not a fault.

Freeze frames

Code	Fuel	Eng temp	Speed / rpm	Set
P0455-00	94 % above 85 %: monitor could not run	63 °C	50.63 km/h / 1391 rpm	360 km ago
P0440-00	92 % above 85 %: monitor could not run	60 °C	40.38 km/h / 1446 rpm	62 km ago
P0456-00	80 %	15 °C	0.00 km/h / 1318 rpm	0 km ago

The EVAP monitor only runs with fuel between 15 and 85 %.