

TrailBeam 500 Headlamp - Charging Troubleshooting

- Confirm the USB-C cable is fully seated in both the headlamp and power source.
- Check the charging indicator light: solid red means charging, solid green means full.
- If no light appears, try a different USB-C cable and a different power source.
- Wipe the charging port gently to remove dust or grit before reconnecting.
- Battery will not charge below freezing; warm the unit to above 32F / 0C first.