

 D593227 performed by: Eduardo Pivaral		Type: Frequent	Date: Apr 13, 2026
Structure: Monorail		Description: (Perris.CA)APPL. 600	Customer: Wabash
Purchase Order: UNAVAILABLE	Job #: 0801344	Location: Outside	Customer Address: 1190 Harley Knox Blvd
Manufacturer:	Serial Number:	Capacity:	Model #:
Crane: no name	Crane: None	Crane: 10,000 lbs	Crane: None
Hoist 1: Konecranes	Hoist 1: 10000791468	Hoist 1: 5 Ton	Hoist 1: CLX250425005
3 Repair	19 Satisfactory Items	0 Safety and Monitor Items	10 N/A Items

🚩 Action Items 3

Monorail:
Beam Bracing

🚩 Repair 📷

Hoist 1:
Lower Block

🚩 Repair 📷

Hoist 1:
Rope/Chain

🚩 Repair 📷

Inspection Overview

Unable to inspect components such as bearings, gearboxes, and any other components that require disassembly to determine condition. 4:28 PM By Eduardo Pivaral

Monorail 6/13 Satisfactory

Capacity Rating	✓ Satisfactory	Beam Level	✓ Satisfactory	Beam Straightness	✓ Satisfactory
Beam Running Flange/Surface	✓ Satisfactory	Beam Splice	N/A	Beam Bracing	🚩 Repair 📷
Suspension Brackets	N/A	Suspension Hardware	N/A	End Stops	✓ Satisfactory
Conductor Bar	N/A	Conductor Bar Brackets	N/A	Clearances	✓ Satisfactory
Transfer Switch	N/A				

Hoist 1 13/19 Satisfactory

Motors	✓ Satisfactory	Brakes	✓ Satisfactory	Control Panel	✓ Satisfactory
Mechanical Brake	✓ Satisfactory	Limit Switches/Stops	✓ Satisfactory	Gear Box	✓ Satisfactory
Fluid Levels/Gaskets/Seals	✓ Satisfactory	Upper Sheaves	N/A	Rope Drum	N/A
Lower Block	🚩 Repair 📷	Rope/Chain	🚩 Repair 📷	Rope/Chain Guides	N/A
Hook	✓ Satisfactory	Couplings	N/A	Wheels/Pinions	✓ Satisfactory
Push Button Station/Radio	✓ Satisfactory	Festoons	✓ Satisfactory	Hoist Brake Operation	✓ Satisfactory
Clearances	✓ Satisfactory				

ACTION LIST - REPAIR ITEMS

Monorail 1 Repair item

Beam Bracing

Repair

1 / 1



Note: Monorail legs are not secured properly.

Hoist 1 2 Repair items

Lower Block

Repair

1 / 1




Note: Lower block rubber cover is damaged.

Rope/Chain

🔧 Repair

1 / 1



Note: Load chain is worn.