Hazard TypeParameter of InterestParameter ValueElectrical Activity SourceField Strength (uT)219High Temperature Heat SourceRadiation Strength (Unitless)0

Hazard X Coordinate

14
-8
0
0