JP1 & JP2 cut to remove DCC Power and ACK JP3 & JP4 cut to remove DCC Power JP5 & JP7 cut to disable led (3V, 5V, VDrive) JP8 solder to power lface from 5V

ורכורכורכור

Dcc Power Distribution Board v0.3.0

GND DCC ACK +5V Vin VDrive Dcc

DCC Signal

+ 12V DC - 12V DC

+ 5V -- VE + + VDrive -