JP1 & JP2 cut to remove DCC Power and ACK JP3 & JP4 cut to remove DCC Power JP5 & JP7 cut to disable led (3V, 5V, VDrive) JP8 solder to power lface from 5V

+ 12V DC - 12V DC

ורכורכורכור

Dcc Power Distribution Board v1.0.0-RC2

GND DCC ACK +5V Vin VDrive Dcc

DCC Signal

+ 5V -- VE + + VDrive -