

FIRE DETECTION AND ALARM SYSTEM INSPECTION AND SERVICING REPORT

Certificate Reference: FD-2025-001

1. DETAILS OF THE CLIENT

Client: ABC Corporation Ltd
Address: 456 Corporate Avenue
London, SW1B 2BB
United Kingdom

2. DETAILS OF THE FIRE DETECTION AND ALARM SYSTEM

Installation Address: 123 Business Street
London, SW1A 1AA
United Kingdom

Details of the system: Conventional fire detection and alarm system with 8 zones covering office spaces, meeting rooms, and common areas

3. EXTENT OF THE INSTALLATION AND LIMITATIONS OF THE INSPECTION AND SERVICING

Extent of the fire detection and alarm system covered by this report:

Complete building coverage including all floors, escape routes, and high-risk areas

Agreed and operational limitations of the inspection and servicing:

System inspection limited to accessible areas only. Roof space detectors not accessible due to ongoing construction work. Agreed with building manager on 06/06/2025.

4. CERTIFICATION OF INSPECTION AND SERVICING

I/we being the competent person(s) responsible (as indicated by my/our signatures below) for the servicing of the fire detection and fire alarm system, particulars of which are set out below, CERTIFY that the said work for which I/we have been responsible complies to the best of my/our knowledge and belief with the recommendations of Clause 45 of BS 5839-1:2017 quarterly inspection of vented batteries/periodic inspection and test/inspection and test over a 12 month period (delete as applicable), except for the variations, if any, stated in this certificate.

Variations from the recommendations of Clause 45 of BS 5839-1:2017:

None - full compliance with BS 5839-1:2017 recommendations

For the INSPECTION and SERVICING of the system:

Name: John Smith
Position: Senior Fire Safety Engineer
Date: 2025-06-06

5. DETAILS OF THE ELECTRICAL CONTRACTOR

Trading Title: Fire Safety Solutions Ltd

Address: 789 Industrial Estate
Birmingham, B12 3CD
United Kingdom

Post Code: B12 3CD

Telephone Number: 0121 456 7890

Registration Number: NICEIC 12345

6. SUMMARY OF THE INSPECTION AND SERVICING

Overall assessment of the inspection and servicing in terms of its suitability for continued use:

☐ SATISFACTORY

* An unsatisfactory assessment indicates that dangerous (Code C1) and/or potentially dangerous (Code C2) conditions have been identified.

7. OBSERVATIONS AND RECOMMENDATIONS FOR ACTIONS TO BE TAKEN

Referring to the attached Schedule(s) of Inspections and Test Results, and subject to the limitations specified on page 1 of this report under 'Extent of the Installation and Limitations of Inspection and Testing':

☐ There are no items adversely affecting operational performance of the fire detection and alarm system

or

☐ The following observations and recommendations are made

C1	Danger Present	Risk of injury. Immediate	remedial action required
C2	Potentially dangerous	Urgent remedial action	required
C3	Improvement	recommended	
FI	Further investigation	required without delay	

Item No	Observations	Classification Code
	No significant issues identified. All systems tested satisfactorily.	

Immediate remedial action required for items:

Urgent remedial action required for items:

Improvement recommended for items:

Further investigation required for items:

8. SUMMARY OF THE INSPECTION AND SERVICING

General condition of the fire detection and alarm system:

The fire detection and alarm system is in good working order with all components functioning correctly. Regular maintenance has been carried out and the system complies with current standards.

Date(s) of the inspection and servicing: 2025-06-06

Outstanding defects reported to responsible person:

None identified during this inspection

☐ Relevant details of the work carried out and faults identified have been entered in the system log book

During the past 12 months 2 false alarms have occurred.

This number of false alarms equates to 6.25 false alarms per 100 automatic fire detectors per annum.

9. NEXT INSPECTION AND SERVICING

Based upon risk assessment, taking into account the type of system and the environment, I/We recommend that this installation is further inspected and serviced after an interval of not more than: 2025-12-06

10. RELATED REFERENCE DOCUMENTS

Related reference documents and certificate numbers:

Installation Certificate FD-2020-001, Previous Service Report FD-2024-002

11. QUARTERLY INSPECTION OF VENTED BATTERIES

☐ Batteries checked

☐ Battery connections checked

☐ Electrolyte levels checked and topped up as necessary

12. SCHEDULE OF ITEMS INSPECTED

Premises

Note that structural or occupancy changes may have affected compliance with BS 5839-1:2017.

- ☐ Manual call points suitably sited
- ☐ Manual call points are unobstructed
- ☐ Manual call points are conspicuous
- ☐ All exits, including any new exits, have manual call points

- ☐ Automatic fire detectors suitable for building use or occupancy
- ☐ Automatic fire detectors suitably sited
- ☐ Fire alarm devices suitably sited
- ☐ No partitions within 500 mm horizontally of any automatic fire detector (Clause 22.3g)
- ☐ No storage within 300 mm of ceilings (Clause 22.3i)
- ☐ Clear space of 500 mm exists below each automatic fire detector (Clause 22.3n)
- ☐ Each automatic fire detector's ability to receive the stimulus it is designed to detect has not been impeded
- ☐ Building use or occupancy does not make existing types of automatic fire detector unsuitable
- ☐ Additional fire detection and alarm equipment provided in any extensions or alterations to the building

13. SCHEDULE OF ITEMS TESTED

- ☐ Fire alarm functions of CIE checked by operation of at least one detector or manual call point in each circuit
- ☐ Operation of fire alarm devices
- ☐ Controls and visual indicators at CIE checked for correct operation
- ☐ Ancillary functions of CIE tested
- ☐ For CIE, manufacturer's checks and tests performed
- ☐ Fault indicators and their circuits checked by simulation of fault conditions
- ☐ Automatic transmission of alarm signal to receiving centre
- ☐ Automatic transmission of other signals, such as fault signals, to receiving centre
- ☐ Radio systems serviced in accordance with manufacturer's recommendations
- ☐ For other equipment, manufacturer's checks and tests performed
- ☐ Printers checked for correct operation
- ☐ Printers checked that characters are legible
- ☐ Print consumables available in sufficient quantity to ensure operation until next service visit
- ☐ Standby battery disconnected and full load alarm simulated
- ☐ Specific gravity of each cell of vented batteries checked
- ☐ Mains disconnected and batteries momentarily load tested