

ELECTRICAL INSTALLATION CONDITION REPORT

Requirements For Electrical Installations - BS 7671 IET Wiring Regulations

Report Reference: CE202695

1 DETAILS OF THE PERSON ORDERING THE REPORT

Client: Highfield Hall Community Centre
Address: Marsh Lane, Farnworth, Bolton

2 REASON FOR PRODUCING THIS REPORT

Reason: Safety assessment requested by client. To assess compliance with BS 7671 (2018) Amendment 2 (2022) and the Electricity at Work Regulations 1989.
Date(s) of Inspection: 15/03/2024

3 DETAILS OF THE INSTALLATION

Installation Address: Marsh Lane, Farnworth, Bolton, BL4 0AW
Description of Premises: Commercial
Estimated Age of Wiring (years): 15
Evidence of Additions/Alterations: Yes
Estimated Age of Additions (years): 5
Installation Records Available? (Reg 651.1): No
Date of Last Inspection: 10/04/2019

4 EXTENT AND LIMITATIONS OF INSPECTION AND TESTING

Extent of Installation Covered: 50% of the installation in accordance with item 3.8.4 of Guidance Note 3. Circuits in the main hall and offices were tested in full; storage and utility areas were visually inspected only.
Agreed Limitations: No testing of HVAC control cables. No lifting of floor boards or inspection of buried conduit. Areas inaccessible due to ongoing building use were excluded from destructive testing.
Agreed With: Mr. J. Hargreaves (Centre Manager)
Operational Limitations: Building in use during inspection. Some circuits could not be de-energised for testing.

5 SUMMARY OF THE CONDITION OF THE INSTALLATION

Overall Assessment: SATISFACTORY

6 RECOMMENDATIONS

Next Inspection Due In:	3 Years
Next Inspection Date:	15/03/2027

7 OBSERVATIONS AND RECOMMENDATIONS FOR ACTIONS TO BE TAKEN		
Item No	Observation	Code
1	Inspection Schedule Item 1.1: The means of isolation (main switch) does not have provision for securing in the off position. Regulation 537.3.2 refers.	C2
2	Inspection Schedule Item 3.4: Conductor insulation is discoloured and shows signs of thermal damage at the connection to luminaire fitting in office 3. Regulation 512.1.1 refers.	C2
3	Inspection Schedule Item 6.2: IP rating of luminaires is not appropriate for Zone 1 in the kitchen area. IP2X or IPXXB minimum is required. Regulation 701.512.2 refers.	C3
4	Inspection Schedule Item 8.1: The external consumer unit cover does not close securely, allowing access to live parts. Regulation 416.1 refers.	C2
5	Inspection Schedule Item 4.3: Single-phase socket outlets installed without additional protection by RCD ("d 30 mA) in a location where use of portable equipment outdoors is reasonably foreseeable. Regulation 411.3.3 refers.	C3
6	Inspection Schedule Item 5.9: Cables in the ceiling void are not adequately supported and are resting on suspended ceiling tiles. Risk of mechanical damage and overheating. Regulation 522.8.5 refers.	C3
7	Inspection Schedule Item 2.7: Earth fault loop impedance for circuit 1 exceeds the maximum value of 1.84 Ω permitted for the installed 16A TCB. Further investigation required to determine cause.	FI

CLASSIFICATION OF OBSERVATION CODES			
C1	C2	C3	FI
Danger Present Risk of injury. Immediate remedial action required	Potentially Dangerous Urgent remedial action required	Improvement Recommended Should be given due consideration	Further Investigation Required Without delay

8 GENERAL CONDITION OF THE INSTALLATION

General Condition:	The installation was found to be in a generally good condition, adequate for continued use. A number of C3 observations were made that should be attended to at the earliest opportunity to ensure continued safety.
---------------------------	--

9 DECLARATION

I/We, being the person(s) responsible for the inspection and testing of the electrical installation (as indicated by my/our signatures below), having exercised reasonable skill and care when carrying out the inspection and testing, hereby declare that the information in this report, including the observations and the attached schedules, provides an accurate assessment of the condition of the electrical installation taking into account the stated extent and limitations in section 4 of this report.

Trading Title:	Cain Enabled Engineering Ltd
Address:	Piccadilly Business Centre, 8 Piccadilly, Manchester, M12 6AE
Registration Number:	611716000
Telephone:	01246 387 450
For Inspection, Testing and Assessment:	
Name:	Daniel Allport
Position:	Qualified Supervisor
Signature:	
Date:	15/03/2024

10 SUPPLY CHARACTERISTICS AND EARTHING ARRANGEMENTS

Earthing Arrangement:	TN-C-S
Nature of Supply:	3-phase (4 wire) ac
Nominal Voltage U / Uo:	400 V / 230 V
Nominal Frequency:	50
Prospective Fault Current (Ipf):	1.8
External Earth Fault Loop Impedance (Ze):	0.13
Supply Protective Device (BS EN / Type / Rating):	BS 1361 BS 1361 Fuse HBC 100A
Short-Circuit Capacity:	33
Number of Supplies:	1
Confirmation of Supply Polarity:	Yes

11 MEANS OF EARTHING / PARTICULARS OF INSTALLATION

Means of Earthing:	Distributor's facility
Maximum Demand (Load):	100 Amps
Protective Measures Against Electric Shock:	ADS (Automatic Disconnection of Supply)

INSPECTOR SIGNATURE:

Name: Daniel Allport
Date: 15/03/2024

CLIENT SIGNATURE:

Name:
Date: