```
**********************
   Keypad Test
**********************
; Created: 10/11/2023 2:18:39 PM
; Author : CAD
start:
   ldi r16, 0xFF //make into output
   out VPORTD_DIR, r16
   ldi r16, 0x00 //make into input
   out VPORTC_DIR, r16
   sbi VPORTB_DIR, 4 ; makes PB4(clear) to output
   cbi VPORTB_DIR, 5 // input directly from pushbutton
wait_for_1:
   sbis VPORTB_IN, 5 ;wait for PB5 being 1
rjmp wait_for_1  ; skip this line if PEO is 1
output:
                 // gets the input from DIP switch and keypad
in r18, VPORTC_IN
mov r18, 19
                 // copy it to another register
                 // complement r19 for display
com r19
out VPORTD_OUT, r19 // display
delay break:
                    ;delay lable for break delay
   ldi r16, 80
   outer_loop_break:
       ldi r17, 133
       inner loop break:
          dec r17
   brne inner_loop_break
       dec r16
brne outer_loop_break
clear_flipflop:
                // clear the flip flop for next input
   cbi VPORTB OUT, 4
   sbi VPORTB_OUT, 4
sbic VPORTB IN, 5
   rjmp delay_break
```