DIFFERENTIAL & DRIVELINE

TABLE OF CONTENTS

	page
PROPELLER SHAFT	1
FRONT AXLE - 181FBI	19
FRONT AXLE - 216FBI	56
REAR AXLE - 194RBI	93
REAR AXLE - 216RBI	131

PROPELLER SHAFT

TABLE OF CONTENTS

	page
PROPELLER SHAFT	
DIAGNOSIS AND TESTING	1
STANDARD PROCEDURE	3
ADJUSTMENTS	5
SPECIFICATIONS	
PROPELLER SHAFT	6
SPECIAL TOOLS	6
SHAFT-PROPELLER FRONT	
REMOVAL	6
INSTALLATION	6
SHAFT-PROPELLER REAR	
REMOVAL	7
INSTALLATION	7
SHAFT-PROPELLER REAR RUBICON	
REMOVAL	7
INSTALLATION	8
UNIVERSAL JOINT-SINGLE CARDAN	
DISASSEMBLY	
DISASSEMBLY	8
DISASSEMBLY - WITH INJECTED RINGS	9
ASSEMBLY	
ASSEMBLY	11
ASSEMBLY - WITH INJECTED RINGS	12
UNIVERSAL JOINT-DOUBLE CARDAN	
DISASSEMBLY	15
ASSEMBLY	16

PROPELLER SHAFT

DIAGNOSIS AND TESTING

VIBRATION

Tires that are out-of-round, or wheels that are unbalanced, will cause a low frequency vibration. Refer to Group 22, Tires and Wheels, for additional information.

Brake drums that are unbalanced will cause a harsh, low frequency vibration. Refer to Group 5, Brakes, for additional information.

Driveline vibration can also result from loose or damaged engine mounts. Refer to Group 9 Engines for additional information.

Propeller shaft vibration increases as the vehicle speed is increased. A vibration that occurs within a specific speed range is not usually caused by a propeller shaft being unbalanced. Defective universal joints, or an incorrect propeller shaft angle, are usually the cause of such a vibration.

DRIVELINE VIBRATION

Drive Condition	Possible Cause	Correction
Propeller Shaft Noise	1) Undercoating or other foreign material on shaft.	1) Clean exterior of shaft and wash with solvent.
	2) Loose U-joint clamp screws.	2) Install new clamps and screws and tighten to proper torque.
	3) Loose or bent U-joint yoke or excessive runout.	3) Install new yoke.