| DRIVE SIDE HEEL TOE | CONDITION | COAST SIDE TOE HEEL | CONDITION | ACTION REQUIRED |
|---|---|---|---|---|
| | **Desirable pattern.** The drive pattern should be centered on the tooth. There should be some clearance between the pattern and the top of the tooth. | | **Desirable pattern.** The coast pattern should be centered on the tooth, but may be slightly toward the toe. There should be some clearance between the pattern and the top of the tooth. | None |
| | **Top heel contact** | | **Top toe contact** | Backlash correct. Thicker pinion position shim required. |
|  | **Root toe contact** |  | **Root heel contact** | Backlash correct. Thinner pinion position shim required. |
| | **Top heel contact** | | **Top heel contact** | Pinion position shim correct. Decrease backlash. |
| | **Root toe contact** | | **Root toe contact** | Pinion position shim correct. Increase backlash. |

8106312d

*Fig. 23 PATTERN INTERPRETATION (GEAR CUT 2 AXIS)*