PEDAL
DESCRIPTION 25
OPERATION 26
REMOVAL 26
INSTALLATION 26
POWER BRAKE BOOSTER
DESCRIPTION 26
OPERATION 26
REMOVAL 27
INSTALLATION 28
COMBINATION VALVE
DESCRIPTION 28
OPERATION 28
DIAGNOSIS AND TESTING - COMBINATION VALVE 28
REMOVAL 29
INSTALLATION 29
ROTORS
DIAGNOSIS AND TESTING
DIAGNOSIS AND TESTING - DISC BRAKE ROTOR 29
DIAGNOSIS AND TESTING - BRAKE DRUM IN HAT ROTOR 30
STANDARD PROCEDURE
STANDARD PROCEDURE - DISC ROTOR MACHINING 30
STANDARD PROCEDURE - BRAKE DRUM IN HAT ROTOR MACHINING 30
REMOVAL
REMOVAL - FRONT 31
REMOVAL - REAR 31
INSTALLATION
INSTALLATION - FRONT 31
INSTALLATION - REAR 32
WHEEL CYLINDERS
REMOVAL 32
DISASSEMBLY 32
CLEANING 32
INSPECTION 32
ASSEMBLY 32
INSTALLATION 32
SUPPORT PLATE
REMOVAL 32
INSTALLATION 33
PARKING BRAKE
DESCRIPTION 34
OPERATION 34
DIAGNOSIS AND TESTING - PARKING BRAKE . 34
SHOES
DESCRIPTION 35
OPERATION 35
REMOVAL 35
CLEANING - REAR DRUM IN HAT BRAKE 35
INSPECTION - REAR DRUM IN HAT BRAKE . . 36
INSTALLATION 36
ADJUSTMENTS
ADJUSTMENT - REAR DRUM IN HAT PARK BRAKE (ROTOR REMOVED) 36
ADJUSTMENT - WITH ADJUSTING TOOL . . . 38
CABLES
REMOVAL
REMOVAL - DRUM BRAKES 38
REMOVAL - DISC BRAKES 39
INSTALLATION
INSTALLATION - DRUM BRAKES 39
INSTALLATION - DISC BRAKES 40

BRAKES - BASE

DESCRIPTION

DESCRIPTION - BRAKE SYSTEM

Power assist front disc and rear drum brakes are standard equipment. Disc brake components consist of single piston calipers and ventilated rotors. Rear drum brakes are dual shoe units with cast brake drums.

The parking brake mechanism is lever and cable operated. The cables are attached to levers on the rear drum brake secondary shoes. The parking brakes are operated by a hand lever.

A dual diaphragm vacuum power brake booster is used for all applications. All models have an aluminum master cylinder with plastic reservoir.

All models are equipped with a combination valve. The valve contains a pressure differential valve and switch and a fixed rate rear proportioning valve.

Factory brake lining on all models consists of an organic base material combined with metallic particles. The original equipment linings do not contain asbestos.