CONDITION	POSSIBLE CAUSES	CORRECTION
	6. Inoperative headlamp leveling switch. 7. Inoperative headlamp leveling motors.	6. Replace headlamp leveling switch. 7. Replace headlamp motors.
MOTORS DO NOT RESPOND TO ONE OR MORE LEVELING POSITION(S)	1. Inoperative headlamp leveling switch. 2. Stuck/Binding or Inoperative motor(s).	1. Replace headlamp leveling switch. 2. Replace headlamp leveling motor(s).