P0522-OIL PRESSURE VOLTAGE LOW 198
P0532-A/C PRESSURE SENSOR LOW 200
P0533-A/C PRESSURE SENSOR HIGH 202
P0551-POWER STEERING SWITCH PERFORMANCE 204
P0562-BATTERY VOLTAGE LOW 206
P0563-BATTERY VOLTAGE HIGH 209
P0572-BRAKE SWITCH NO.1 CIRCUIT LOW 211
P0573-BRAKE SWITCH NO.1 CIRCUIT HIGH 213
P0580-SPEED CONTROL SWITCH NO.1 LOW 215
P0581-SPEED CONTROL SWITCH NO.1 HIGH 217
P0582-SPEED CONTROL VACUUM SOLENOID CIRCUIT 220
P0586-SPEED CONTROL VENT SOLENOID CIRCUIT 223
P0594-SPEED CONTROL SERVO POWER CIRCUIT 226
P0600-SERIAL COMMUNICATION LINK 229
P0601-INTERNAL MEMORY CHECKSUM INVALID 229
P0622-GENERATOR FIELD CONTROL CIRCUIT 230
P0627-FUEL PUMP RELAY CIRCUIT 232
P0630-VIN NOT PROGRAMMED IN PCM 234
P0632-ODOMETER NOT PROGRAMMED IN PCM 235
P0633-SKIM KEY NOT PROGRAMMED IN PCM 236
P0645-A/C CLUTCH RELAY CIRCUIT 237
P0685-ASD RELAY CONTROL CIRCUIT 239
P0688-ASD RELAY SENSE CIRCUIT LOW 241
P0700-TRANSMISSION CONTROL SYSTEM (MIL REQUEST) 244
P0850-PARK/NEUTRAL SWITCH PERFORMANCE 245
P1115-GENERAL TEMPERATURE SENSOR PERFORMANCE 247
P1593-SPEED CONTROL SWITCH NO.1 STUCK 249
P1603-PCM INTERNAL DUAL-PORT RAM COMMUNICATION 252
P1604-PCM INTERNAL DUAL-PORT RAM READ/WRITE INTEGRITY FAILURE . . . 252
P1607-PCM INTERNAL SHUTDOWN TIMER RATIONALITY 252
P1696-PCM FAILURE EEPROM WRITE DENIED 254
P1697-PCM FAILURE SRI MILES NOT STORED 254
P2096-DOWN STREAM FUEL TRIM LEAN BANK 1 256
P2097-DOWN STREAM FUEL TRIM RICH BANK 1 256
P2098-DOWN STREAM FUEL TRIM LEAN BANK 2 256
P2099-DOWN STREAM FUEL TRIM RICH BANK 2 256
P2302-IGNITION COIL NO.1 SECONDARY CIRCUIT- INSUFFICIENT IONIZATION 259
P2305-IGNITION COIL NO.2 SECONDARY CIRCUIT- INSUFFICIENT IONIZATION 259
P2308-IGNITION COIL NO.3 SECONDARY CIRCUIT- INSUFFICIENT IONIZATION 259
P2503-CHARGING SYSTEM OUTPUT LOW 262
U0101-NO BUS MESSAGE FROM TRANS CONTROL MODULE 265
U0155-NO CLUSTER BUS MESSAGE 267
U0168-NO SKIM BUS MESSAGE 268
*CHECKING A/C SYSTEM OPERATION WITH NO DTCS 270
*CHECKING PCM POWERS AND GROUNDS 274

STARTING
*CHECKING FUEL DELIVERY 275
*CHECKING HARD START (FUEL DELIVERY SYSTEM) 278
*ENGINE CRANKS DOES NOT START 280