P1797-MANUAL SHIFT OVERHEAT 423
*BACKUP LAMPS COME ON WHILE SHIFTER IS NOT IN REVERSE POSITION. .425
*BACKUP LAMPS INOPERATIVE 427
*CHECKING PARK/NEUTRAL SWITCH OPERATION 430
*INCORRECT TRANSMISSION FLUID LEVEL. 432
*NO SPEEDOMETER OPERATION. 433
*TRANSMISSION NOISY WITH NO DTC'S PRESENT 434
*TRANSMISSION SHIFTS EARLY WITH NO DTC'S 435
*TRANSMISSION SIMULATOR 8333 WILL NOT POWER UP 436

VEHICLE THEFT/SECURITY
ANTENNA FAILURE 437
COP FAILURE. 437
EEPROM FAILURE. 437
INTERNAL FAULT. 437
RAM FAILURE. 437
SERIAL LINK INTERNAL FAULT 437
STACK OVERFLOW FAILURE. 437
PCM STATUS FAILURE 439
SERIAL LINK EXTERNAL FAULT 439
ROLLING CODE FAILURE. 441
VIN MISMATCH. 441
TRANSPONDER COMMUNICATION FAILURE 443
TRANSPONDER CYCLIC REDUNDANCY CHECK (CRC) FAILURE 443
TRANSPONDER ID MISMATCH 443
TRANSPONDER RESPONSE MISMATCH. 443

VERIFICATION TESTS
VERIFICATION TESTS. 446

8.0 COMPONENT LOCATIONS. 453

8.1 CONTROL MODULES AND PDC. 453
8.2 DATA LINK CONNECTOR 453
8.3 SENSORS AND SOLENOIDS 454
8.4 FUEL SYSTEM 457
8.5 SWITCHES 458

9.0 CONNECTOR PINOUTS 459

A/C COMPRESSOR CLUTCH - BLACK 2 WAY 459
A/C HIGH PRESSURE SWITCH (4.0L) - BLACK 2 WAY. 459
A/C LOW PRESSURE SWITCH - GREEN 2 WAY 459
A/C PRESSURE TRANSDUCER (2.4L) - 4 WAY 459
AMBIENT TEMPERATURE SENSOR (ENGINE) - 2 WAY 460
BATTERY TEMPERATURE SENSOR - BLACK 2 WAY 460
BRAKE LAMP SWITCH - GRAY 6 WAY 460
C102 - (ENGINE SIDE). 461
C102 - GRAY (HEADLAMP AND DASH SIDE) 461
C103 - BLACK (ENGINE SIDE) 462
C103 - BLACK (HEADLAMP AND DASH SIDE) 462
C104 (RHD) - BLACK (ENGINE SIDE) 462
C104 (RHD) - BLACK (HEADLAMP AND DASH SIDE) 463
C181 (2.4L) - BLACK (ENGINE INTAKE SIDE) 463