P1696-PCM FAILURE EEPROM WRITE DENIED — Continued

TEST	ACTION	APPLICABILITY
3	With the DRBIII®, perform the SRI Memory Test a third time. **NOTE: Retest the SRI Memory two more times.** Does the DRBIII® display Write Refused again? Yes → Replace and program the Powertrain Control Module per Service Information. Perform POWERTRAIN VERIFICATION TEST VER - 1. No → Test Complete.	All
4	With the DRBIII®, perform the SRI Memory Test. Does the DRBIII® display SRI Mileage Invalid? Yes → Update the mileage and retest the SRI Memory. Perform POWERTRAIN VERIFICATION TEST VER - 1. No → Go To 5	All
5	Compare the SRI Mileage stored with the Instrument Panel Odometer. Is the mileage within the specified range displayed on the DRBIII®? Yes → Test Complete. No → Update the mileage and retest the SRI Memory. Perform POWERTRAIN VERIFICATION TEST VER - 1.	All