DIFFERENTIAL & DRIVELINE

TABLE OF CONTENTS

	page
PROPELLER SHAFT	1
FRONT AXLE - 181FBI	15
FRONT AXLE - 216FBI	49
REAR AXLE - 194RBI	84
REAR AXLE - 216RBI	118

PROPELLER SHAFT

TABLE OF CONTENTS

	page
PROPELLER SHAFT	
DIAGNOSIS AND TESTING	1
STANDARD PROCEDURE	4
ADJUSTMENTS	6
SPECIFICATIONS	
PROPELLER SHAFT	6
SPECIAL TOOLS	7
PROPELLER SHAFT - FRONT	
REMOVAL	7
INSTALLATION	7
PROPELLER SHAFT - REAR	
REMOVAL	7
INSTALLATION	8
PROPELLER SHAFT - REAR RUBICON	
REMOVAL	8
INSTALLATION	9
SINGLE CARDAN UNIVERSAL JOINTS	
DISASSEMBLY	9
ASSEMBLY	10
DOUBLE CARDAN UNIVERSAL JOINTS	
DISASSEMBLY	11
ASSEMBLY	12

PROPELLER SHAFT

DIAGNOSIS AND TESTING

VIBRATION

Tires that are out-of-round, or wheels that are unbalanced, will cause a low frequency vibration. Refer to Group 22, Tires and Wheels, for additional information.

Brake drums that are unbalanced will cause a harsh, low frequency vibration. Refer to Group 5, Brakes, for additional information.

Driveline vibration can also result from loose or damaged engine mounts. Refer to Group 9 Engines for additional information.

Propeller shaft vibration increases as the vehicle speed is increased. A vibration that occurs within a specific speed range is not usually caused by a propeller shaft being unbalanced. Defective universal joints, or an incorrect propeller shaft angle, are usually the cause of such a vibration.