TABLE OF CONTENTS - Continued

P0218-HIGH TEMPERATURE OPERATION ACTIVATED 277
P0562-LOW BATTERY VOLTAGE 279
P0604-INTERNAL TCM 282
P0605-INTERNAL TCM 283
P0613-INTERNAL TCM 284
P0706-CHECK SHIFTER SIGNAL 285
P0711-TRANSMISSION TEMPERATURE SENSOR PERFORMANCE 291
P0712-TRANSMISSION TEMPERATURE SENSOR LOW 294
P0713-TRANSMISSION TEMPERATURE SENSOR HIGH 297
P0714-TRANSMISSION TEMPERATURE SENSOR INTERMITTENT 300
P0715-INPUT SPEED SENSOR ERROR 302
P0720-OUTPUT SPEED SENSOR ERROR 306
P0725-ENGINE SPEED SENSOR CIRCUIT 310
P0731-GEAR RATIO ERROR IN 1ST 313
P0732-GEAR RATIO ERROR IN 2ND 315
P0733-GEAR RATIO ERROR IN 3RD 318
P0734-GEAR RATIO ERROR IN 4TH 321
P0736-GEAR RATIO ERROR IN REVERSE 324
P0740-TCC OUT OF RANGE 326
P0750-LR SOLENOID CIRCUIT 328
P0755-2/4 SOLENOID CIRCUIT 332
P0760-OD SOLENOID CIRCUIT 336
P0765-UD SOLENOID CIRCUIT 340
P0841-LR PRESSURE SWITCH SENSE CIRCUIT 344
P0845-2/4 HYDRAULIC PRESSURE TEST FAILURE 348
P0846-2/4 PRESSURE SWITCH SENSE CIRCUIT 352
P0870-OD HYDRAULIC PRESSURE TEST FAILURE 356
P0871-OD PRESSURE SWITCH SENSE CIRCUIT 360
P0882-TCM POWER INPUT LOW 364
P0888-RELAY OUTPUT ALWAYS OFF 364
P0883-TCM POWER INPUT HIGH 367
P0891-TRANSMISSION RELAY ALWAYS ON 367
P0884-POWER UP AT SPEED 370
P0888-RELAY OUTPUT ALWAYS OFF 371
P0890-SWITCHED BATTERY 373
P0891-TRANSMISSION RELAY ALWAYS ON 375
P0897-WORN OUT/BURNT TRANSAXLE FLUID 378
P0944-LOSS OF PRIME 380
P0992- 2-4/OD HYDRAULIC PRESSURE TEST FAILURE 383
P1652-SERIAL COMMUNICATION LINK MALFUNCTION 385
P1684-BATTERY WAS DISCONNECTED 387
P1687-NO COMMUNICATION WITH THE MIC 390
P1694-BUS COMMUNICATION WITH ENGINE MODULE 392
P1713-RESTRICTED MANUAL VALVE IN T2 RANGE 394
P1775-SOLENOID SWITCH VALVE LATCHED IN TCC POSITION 395
P1776-SOLENOID SWITCH VALVE LATCHED IN LR POSITION 399
P1790-FAULT IMMEDIATELY AFTER SHIFT 403
P1793-TRD LINK COMMUNICATION ERROR 404
P1794-SPEED SENSOR GROUND ERROR 407
P1797-MANUAL SHIFT OVERHEAT 409
*BACKUP LAMPS COME ON WHILE SHIFTER IS NOT IN REVERSE POSITION . .411
*BACKUP LAMPS INOPERATIVE 413
*CHECKING PARK/NEUTRAL SWITCH OPERATION 416