*INCORRECT TRANSMISSION FLUID LEVEL 418
*NO SPEEDOMETER OPERATION 419
*TRANSMISSION NOISY WITH NO DTC'S PRESENT 420
*TRANSMISSION SHIFTS EARLY WITH NO DTC'S 421
*TRANSMISSION SIMULATOR 8333 WILL NOT POWER UP 422

VEHICLE THEFT/SECURITY
ANTENNA FAILURE 423
COP FAILURE 423
EEPROM FAILURE 423
INTERNAL FAULT 423
RAM FAILURE 423
SERIAL LINK INTERNAL FAULT 423
STACK OVERFLOW FAILURE 423
PCM STATUS FAILURE 425
SERIAL LINK EXTERNAL FAULT 425
ROLLING CODE FAILURE 427
VIN MISMATCH 427
TRANSPONDER COMMUNICATION FAILURE 429
TRANSPONDER CYCLIC REDUNDANCY CHECK (CRC) FAILURE 429
TRANSPONDER ID MISMATCH 429
TRANSPONDER RESPONSE MISMATCH 429

VERIFICATION TESTS
VERIFICATION TESTS 432

8.0 COMPONENT LOCATIONS 441

8.1 CONTROL MODULES AND PDC 441
8.2 DATA LINK CONNECTOR 441
8.3 SENSORS AND SOLENOIDS 442
8.4 FUEL SYSTEM 445
8.5 SWITCHES 446

9.0 CONNECTOR PINOUTS 447

A/C COMPRESSOR CLUTCH - BLACK 2 WAY 447
A/C HIGH PRESSURE SWITCH (4.0L) - BLACK 2 WAY 447
A/C LOW PRESSURE SWITCH - GREEN 2 WAY 447
A/C PRESSURE TRANSDUCER (2.4L) - 4 WAY 447
AMBIENT TEMPERATURE SENSOR (ENGINE) - 2 WAY 448
BRAKE LAMP SWITCH - GRAY 6 WAY 448
C102 - (ENGINE SIDE) 448
C102 - GRAY (HEADLAMP AND DASH SIDE) 449
C103 - BLACK (ENGINE SIDE) 449
C103 - BLACK (HEADLAMP AND DASH SIDE) 450
C104 (RHD) - BLACK (ENGINE SIDE) 450
C104 (RHD) - BLACK (HEADLAMP AND DASH SIDE) 450
C181 (2.4L) - BLACK (ENGINE INTAKE SIDE) 450
C181 (2.4L) - BLACK (ENGINE SIDE) 451
C182 (2.4L) - BLACK (ENGINE INTAKE SIDE) 451
C182 (2.4L) - BLACK (ENGINE SIDE) 452
CAMSHAFT POSITION SENSOR - BLACK 3 WAY 452
CLOCKSPRING C1 - 4 WAY 452