Symptom:

P0073-AMBIENT TEMP SENSOR CIRCUIT HIGH

When Monitored and Set Condition:

P0073-AMBIENT TEMP SENSOR CIRCUIT HIGH

When Monitored: The ignition key on.

Set Condition: The Ambient Temperature Sensor voltage is greater than 4.94 volts at the PCM for 4.8 seconds. Three good trips to clear the MIL.

POSSIBLE CAUSES
AAT SENSOR VOLTAGE ABOVE 4.8 VOLTS
AAT SENSOR
(G31) AAT SIGNAL CIRCUIT SHORTED TO BATTERY VOLTAGE
(G31) AAT SIGNAL CIRCUIT OPEN
(K900) SENSOR GROUND CIRCUIT OPEN
PCM

TEST	ACTION	APPLICABILITY
1	Ignition on, engine not running. With the DRBIII®, read the Ambient Temperature Sensor voltage. Is the voltage above 4.8 volts? Yes → Go To 2 No → Refer to the INTERMITTENT CONDITION Symptom (Diagnostic Procedure). Perform POWERTRAIN VERIFICATION TEST VER - 5.	All
2	Turn the ignition off. Disconnect the Ambient Temperature Sensor harness connector. Connect a jumper wire between the (G31) AAT Signal circuit and the (K900) Sensor ground circuit at the AAT Sensor harness connector. Ignition on, engine not running. With the DRBIII®, read Ambient Temperature Sensor voltage. Is the voltage below 1.0 volt? Yes → Replace the Ambient Temperature Sensor. Perform POWERTRAIN VERIFICATION TEST VER - 5. No → Go To 3 **NOTE: Remove the jumper wire before continuing.**	All