## Symptom:

## P0580-SPEED CONTROL SWITCH NO.1 LOW

**When Monitored and Set Condition:**

**P0580-SPEED CONTROL SWITCH NO.1 LOW**

When Monitored: With the ignition key on. Battery voltage above 10 volts.

Set Condition: When switch voltage is less than 0.60 of a volt for 2 minutes.

| POSSIBLE CAUSES |
|---|
| SPEED CONTROL SWITCH VOLTAGE LOW |
| SPEED CONTROL ON/OFF SWITCH |
| SPEED CONTROL RESUME/ACCEL SWITCH |
| CLOCKSPRING |
| (V37) S/C SIGNAL CIRCUIT SHORTED TO THE (K900) SENSOR GROUND CIRCUIT |
| (V37) S/C SIGNAL CIRCUIT SHORTED TO GROUND |
| PCM |

| TEST | ACTION | APPLICABILITY |
|---|---|---|
| 1 | **NOTE: Do not press any of the Speed Control Switch buttons.**<br>Ignition on, engine not running.<br>With the DRBIII®, read the Speed Control voltage.<br>Is the Speed Control voltage below 1.0 volt?<br>Yes → Go To 2<br>No → Refer to the INTERMITTENT CONDITION Symptom (Diagnostic Procedure).<br>Perform POWERTRAIN VERIFICATION TEST VER - 4. | All |
| 2 | With the DRBIII®, monitor the Speed Control Switch voltage.<br>Disconnect the Speed Control On/Off Switch harness connector.<br>Did the voltage change to above 4.7 volts?<br>Yes → Replace the Speed Control On/Off Switch.<br>Perform POWERTRAIN VERIFICATION TEST VER - 4.<br>No → Go To 3 | All |
| 3 | With the DRBIII®, monitor the Speed Control Switch voltage.<br>Disconnect the Speed Control Resume/Accel Switch harness connector.<br>Did the voltage change to above 4.7 volts?<br>Yes → Replace the Speed Control Resume/Accel Switch.<br>Perform POWERTRAIN VERIFICATION TEST VER - 4.<br>No → Go To 4 | All |