Symptom:

P1593-SPEED CONTROL SWITCH NO.1 STUCK

When Monitored and Set Condition:

P1593-SPEED CONTROL SWITCH NO.1 STUCK

When Monitored: Ignition on.

Set Condition: S/C Switche #1 is mechanically stuck in the On/Off, Resume/Accel, or Set position for too long. One trip fault.

POSSIBLE CAUSES
SPEED CONTROL SWITCH STATUS
SPEED CONTROL SWITCHES
(V37) S/C SIGNAL CIRCUIT SHORTED TO THE (K900) SENSOR GROUND CIRCUIT
(V37) S/C SIGNAL CIRCUIT SHORTED TO GROUND
(V37) S/C SIGNAL CIRCUIT SHORTED TO BATTERY VOLTAGE
(V37) S/C SIGNAL CIRCUIT OPEN
(K900) SENSOR GROUND CIRCUIT OPEN
PCM

TEST	ACTION	APPLICABILITY
1	Start the engine. With the DRBIII®, monitor each switch function for the Speed Control Switches. Press and release each Speed Control Button. - Resume/Accel - Cancel - Decel (Coast) - On/Off - Set Does each switch function change status when pressing and then depressing each switch? Yes → Refer to the INTERMITTENT CONDITION Symptom (Diagnostic Procedure). Perform POWERTRAIN VERIFICATION TEST VER - 4. No → Go To 2	All