Symptom List:

P1603-PCM INTERNAL DUAL-PORT RAM COMMUNICATION
P1604-PCM INTERNAL DUAL-PORT RAM READ/WRITE INTEGRITY FAILURE
P1607-PCM INTERNAL SHUTDOWN TIMER RATIONALITY
P2610-PCM INTERNAL ENGINE OFF TIMER RATIONALITY

Test Note: All symptoms listed above are diagnosed using the same tests. The title for the tests will be P1603-PCM INTERNAL DUAL-PORT RAM COMMUNICATION.

When Monitored and Set Condition:

P1603-PCM INTERNAL DUAL-PORT RAM COMMUNICATION

When Monitored: Ignition off, on, and run/start.

Set Condition: Internal PCM failure detected. Intermittent open on PCM Connector 1, pin 12, (F11) Fused Ignition Switch Output circuit.

P1604-PCM INTERNAL DUAL-PORT RAM READ/WRITE INTEGRITY FAILURE

When Monitored: Ignition off, on, and run/start.

Set Condition: Internal PCM failure detected. Intermittent open on PCM Connector 1, pin 12, (F11) Fused Ignition Switch Output circuit.

P1607-PCM INTERNAL SHUTDOWN TIMER RATIONALITY

When Monitored: Ignition on.

Set Condition: Internal PCM failure detected.

P2610-PCM INTERNAL ENGINE OFF TIMER RATIONALITY

When Monitored: Ignition on.

Set Condition: A rationality error has been detected for the PCM internal engine off timer performance test. Two trip fault. Internal PCM failure detected.

POSSIBLE CAUSES
PCM FUSED IGNITION SWITCH OUTPUT CIRCUIT
PCM