U0101-NO BUS MESSAGE FROM TRANS CONTROL MODULE — Continued

TEST	ACTION	APPLICABILITY
3	**NOTE: Determine which modules this vehicle is equipped with before beginning.** **NOTE: When attempting to communicate with any of the modules on this vehicle, the DRBIII® will display 1 of 2 different communication errors: a NO RESPONSE message or a BUS +/- SIGNALS OPEN MESSAGE.** Ignition on, engine not running. Use the DRBIII®, attempt to communicate with the remaining control modules. Was the DRBIII® able to communicate with one or more of the Modules? Yes → Replace and program the Powertrain Control Module per Service Information. Perform POWERTRAIN VERIFICATION TEST VER - 1. No → Refer to the COMMUNICATION category and perform the PCI BUS COMMUNICATION FAILURE Symptom. Perform POWERTRAIN VERIFICATION TEST VER - 1.	All