Symptom:

***TRANSMISSION SIMULATOR 8333 WILL NOT POWER UP**

TEST	ACTION	APPLICABILITY
1	**NOTE: If the Transmission Simulator Miller tool #8333 will not power up, this is a symptom of the Transmission Relay being open, such as Limp-in, and/or this also could be a indication of the Transmission Simulator not installed correctly on the vehicle.** **NOTE: Check the Simulator ground cable connection.** **NOTE: Check all Transmission Simulator harness connections.** Repair these symptoms before having the Transmission Simulator Miller Tool #8333 repaired. Continue Test Complete.	All