

5.1 FOUNDATION AND TOWER (EXTERNAL)

Móng và thân tháp (bên ngoài)

3 findings

3 medium

6 ảnh / photos

2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM



Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM



Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM

Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



5.2 TOWER BASE AND BASEMENT

Đế tháp và tầng hầm

1 finding


1 medium

2 ảnh / photos

2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM

Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



5.3 TOWER SECTION BASE-D

Đoạn tháp Base-D

4 findings

4 medium

8 ảnh / photos

2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM


Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM


Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM


Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM

Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



5.4 TOWER SECTION D-C

Đoạn tháp D-C

2 findings

2 medium 4 ảnh / photos

2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM


Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM

Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



5.5 TOWER SECTION C-B

Đoạn tháp C-B

5 findings

5 medium 10 ảnh / photos

2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM


Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM



Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM


Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM




Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM

Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



5.6 TOWER SECTION B-A

Đoạn tháp B-A


1 finding

1 medium 2 ảnh / photos

2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM

Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



5.7 TOWER SECTION A-TOP

3 findings

Đoạn tháp A-Top

3 medium 6 ảnh / photos

2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM


Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM


Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM

Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



5.8 TOP SECTION AND YAW PLATFORM

2 findings

Đoạn đỉnh và sàn yaw

2 medium 4 ảnh / photos

2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM



Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM

Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



5.9 ELEVATOR, LADDER AND ACCESS SYSTEM

Thang máy, thang leo và lối tiếp cận

4 findings


4 medium

8 ảnh / photos

2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM


Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM


Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM



Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM

Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



5.10 ROTOR HUB AND PITCH SYSTEM

1 finding

Hub và hệ pitch

1 medium 2 ảnh / photos

2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM

Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



5.11 NACELLE

2 findings


Khoang máy

2 medium 4 ảnh / photos

2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM


Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM

Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



5.12 ROTOR, MAIN SHAFT AND MAIN BEARING

3 findings

Rotor, trục chính và ổ đỡ chính

3 medium 6 ảnh / photos

2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM


Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM

Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — Nacelle — Gearbox

M3 · MEDIUM

Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.

