

5.1 FOUNDATION AND TOWER (EXTERNAL)

Móng và thân tháp (bên ngoài)

3 findings


3 medium

6 ảnh / photos

2026-09-15 — «S1F1» Nacelle — Gearbox

M3 · MEDIUM



«S1F1» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — «S1F2» Nacelle — Gearbox

M3 · MEDIUM


«S1F2» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — «S1F3» Nacelle — Gearbox

M3 · MEDIUM

«S1F3» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



5.2 TOWER BASE AND BASEMENT

Đế tháp và tầng hầm

1 finding

1 medium

2 ảnh / photos

2026-09-15 — «S2F1» Nacelle — Gearbox

M3 · MEDIUM

«S2F1» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



5.3 TOWER SECTION BASE-D

Đoạn tháp Base-D

4 findings


4 medium

8 ảnh / photos

2026-09-15 — «S3F1» Nacelle — Gearbox

M3 · MEDIUM



«S3F1» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — «S3F2» Nacelle — Gearbox

M3 · MEDIUM



«S3F2» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — «S3F3» Nacelle — Gearbox

M3 · MEDIUM


«S3F3» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — «S3F4» Nacelle — Gearbox

M3 · MEDIUM

«S3F4» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



5.4 TOWER SECTION D–C

Đoạn tháp D–C

2 findings


2 medium

4 ảnh / photos

2026-09-15 — «S4F1» Nacelle — Gearbox

M3 · MEDIUM



«S4F1» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — «S4F2» Nacelle — Gearbox

M3 · MEDIUM

«S4F2» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



5.5 TOWER SECTION C–B

Đoạn tháp C–B

5 findings


5 medium

10 ảnh / photos

2026-09-15 — «S5F1» Nacelle — Gearbox

M3 · MEDIUM


«S5F1» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — «S5F2» Nacelle — Gearbox

M3 · MEDIUM


«S5F2» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — «S5F3» Nacelle — Gearbox

M3 · MEDIUM


«S5F3» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — «S5F4» Nacelle — Gearbox

M3 · MEDIUM


«S5F4» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — «S5F5» Nacelle — Gearbox

M3 · MEDIUM

«S5F5» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



5.6 TOWER SECTION B-A

Đoạn tháp B-A

1 finding


1 medium

2 ảnh / photos

2026-09-15 — «S6F1» Nacelle — Gearbox

M3 · MEDIUM

«S6F1» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



5.7 TOWER SECTION A-TOP

Đoạn tháp A-Top

3 findings


3 medium

6 ảnh / photos

2026-09-15 — «S7F1» Nacelle — Gearbox

M3 · MEDIUM



«S7F1» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — «S7F2» Nacelle — Gearbox

M3 · MEDIUM


«S7F2» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — «S7F3» Nacelle — Gearbox

M3 · MEDIUM

«S7F3» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



5.8 TOP SECTION AND YAW PLATFORM

2 findings

Đoạn đỉnh và sàn yaw


2 medium

4 ảnh / photos

2026-09-15 — «S8F1» Nacelle — Gearbox

M3 · MEDIUM



«S8F1» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — «S8F2» Nacelle — Gearbox

M3 · MEDIUM

«S8F2» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



5.9 ELEVATOR, LADDER AND ACCESS SYSTEM

4 findings

Thang máy, thang leo và lối tiếp cận


4 medium

8 ảnh / photos

2026-09-15 — «S9F1» Nacelle — Gearbox

M3 · MEDIUM


«S9F1» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — «S9F2» Nacelle — Gearbox

M3 · MEDIUM



«S9F2» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — «S9F3» Nacelle — Gearbox

M3 · MEDIUM




«S9F3» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — «S9F4» Nacelle — Gearbox

M3 · MEDIUM

«S9F4» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



5.10 ROTOR HUB AND PITCH SYSTEM

Hub và hệ pitch

1 finding


1 medium

2 ảnh / photos

2026-09-15 — «S10F1» Nacelle — Gearbox

M3 · MEDIUM

«S10F1» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



5.11 NACELLE

Khoang máy

2 findings


2 medium

4 ảnh / photos

2026-09-15 — «S11F1» Nacelle — Gearbox

M3 · MEDIUM



«S11F1» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — «S11F2» Nacelle — Gearbox

M3 · MEDIUM

«S11F2» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



5.12 ROTOR, MAIN SHAFT AND MAIN BEARING

Rotor, trục chính và ổ đỡ chính

3 findings


3 medium

6 ảnh / photos

2026-09-15 — «S12F1» Nacelle — Gearbox

M3 · MEDIUM


«S12F1» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — «S12F2» Nacelle — Gearbox

M3 · MEDIUM

«S12F2» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.



2026-09-15 — «S12F3» Nacelle — Gearbox

M3 · MEDIUM

«S12F3» Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below the joint.

