

5.11 NACELLE

Khoang máy

10 findings

3 critical

4 medium

3 low

30 ảnh / photos

2026-08-21 — [1] Nacelle — Gearbox

M2 · LOW

[1] Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below.

4:3

2026-08-21 — [2] Tower section D-C

M3 · MEDIUM

[2] Rust on the ladder bracket at two positions.

4:3

dọc

2026-08-21 — [3] Nacelle — Yaw deck

M4 · CRITICAL

[3] Grease residue on the yaw deck, no damage observed.

REQUIRES IMMEDIATE ATTENTION

4:3

dọc

rộng

2026-08-21 — [4] Generator — Cooling

M2 · LOW

[4] Cooling fin bent at the lower right corner of the radiator block.

4:3

dọc

rộng

1:1

2026-08-21 — [5] Nacelle top —
Anchor points

M3 · MEDIUM

[5] Anchor point coating worn at two of the four positions on the nacelle roof.




2026-08-21 — [6] Nacelle —
Gearbox

M4 · CRITICAL

[6] Oil seepage at the housing joint; the surrounding paint has started to flake and rust is visible on the bracket below.


REQUIRES IMMEDIATE ATTENTION



2026-08-21 — [7] Tower section D-
C

M2 · LOW

[7] Rust on the ladder bracket at two positions.



2026-08-21 — [8] Nacelle — Yaw
deck

M3 · MEDIUM

[8] Grease residue on the yaw deck, no damage observed.







2026-08-21 — [9] Generator —
Cooling

M4 · CRITICAL

[9] Cooling fin bent at the lower right corner of the radiator block.

REQUIRES IMMEDIATE ATTENTION



2026-08-21 — [10] Nacelle top —
Anchor points

M2 · LOW

[10] Anchor point coating worn at two of the four positions on the nacelle roof.

