Sensors Signals Report

dario

December 2019

1 Introduction

Second Order Transfer Function

$$c\ddot{y}(t) + b\dot{y}(t) + ay(t) = e\dot{u}(t) + fu(t)$$
(1)

Solving via Laplace:

$$\frac{Y(s)}{U(s)} = \frac{es+f}{cs^2+bs+a} \tag{2}$$