PIC16F684 Line-Following Robot

Dar Mehta January 15, 2015

Contents

1	Abstract				
2	Objective				
3	Components				
	3.1	PIC16F684 Microcontroller	4		
	3.2	L293DNE Motor Controller	4		
	3.3	LM7805 Voltage Regulator	4		
			4		
	3.5	Breadboard			
4	Design				
	4.1	Code	5		
	4.2		6		
	4.3		6		
			7		
5	Problem Diagnosis and Correction				
6	Conclusion				
7	App	pendix	10		
	7.1^{-}	Final Code	10		

1 Abstract

The robot is designed to follow a specified black line made out of electrical tape on a white surface. The programming was done using the assembly language on the PIC 16F684 microcontroller (herein referred to as PIC microcontroller), whereas the motor control was handled by the L293DNE chip.

This report details the design and development of the line following robot including the purpose, materials and the initial and final designs of the robot. The construction of the robot involved the mounting of two light sensors, the PIC microcontroller and a breadboard for the circuit onto a pre-built robot chassis. Furthermore, this report also includes a detailed step-by-step construction of the robot that the reader can follow to recreate the robot. Lastly, the report includes problem diagnosis stating the description and root cause, symptoms, and solutions and design changes. The appendix includes layout diagrams of the robot and the circuit as well as pictures of the final robot, program flowchart, the final code and links to datasheets for the components used are located in the appendix.

2 Objective

The objective of this project, as assigned in class, is to build an autonomous line following robot using the PIC microcontroller and light sensors. The two light sensors are used to allow the robot to detect a black line on a white surface while the L293DNE controls the movement of the robot.

The original goal of the robot was to use an algorithm that will keep the robot centred on the black line while it completes one lap of a track outlined with black electrical tap on a white surface in 60 seconds. However, midway through the project, due to technical difficulties combined with time constraints, the goal was changed so that the robot is using a hardcoded algorithm that will allow the robot to complete the track from point A to point B in 45 seconds. In these 45 seconds, the robot must start at one end of the course, reach the other end, and come to a complete stop at the end of the track.

3 Components

3.1 PIC16F684 Microcontroller

The Peripheral Interface Controller is a chip consisting of 14 pins and will be used as the brain of the robot in order to control its motors and sensors. A program is written in assembly on a compatible IDE such as MP LAB. It is then built, compiled and uploaded by the IDE to the microcontroller. This program is run by applying +5V of power to the chip. The pins on the controller can be configured for output or input in order to either control a device such has a motor or read data from a device such as a light sensor, respectively.

3.2 L293DNE Motor Controller

The L293DNE motor controller has 16 pins and is connected to each of the two motors. It is also connected to the PIC Microcontroller in order to be able to control the start/stop and direction of each motor. Pins 1, 8, 9, and 16 are connected to the power supply via an LM7805 Voltage Regulator which provides 5V. Pins 4, 5, 12 and 13 are grounded. Motor 1 is connected to pins 3 and 6 and is controlled by pins 2 and 7. Motor 2 is connected to pins 11 and 14 and is controlled by pins 10 and 15. Pins 2, 7, 10 and 15 which control the two motors are connected to the output pins on the PIC microcontroller. See data sheet in references section below for more details.

3.3 LM7805 Voltage Regulator

The LM7805 voltage regulator is connected to the robots circuit in order to ensure no components are damaged due to excess voltage. It consists of three pins: an input which takes in any input voltage, a ground, and an output which outputs a safe voltage of 5V.

3.4 QRD1114 Sensors (x2)

The QRD1114 is a light sensor consisting of four pins - a cathode, an anode, an emitter and a collector. Refer to the datasheet in the references section below for more details about each of the four pins. The sensor emits infrared light that is powered constantly and detects the reflectivity of this emitted

light. Typically, the darker the surface, the more the light is absorbed and so less light is detected by the phototransistor. When light is detected by the phototransistor, current flows through the sensor thus sending an analog signal to the PIC microcontroller. This allows the sensor to differentiate between black and white surfaces.

3.5 Breadboard

A breadboard is used for easy construction and debugging of the robots circuit as it requires no soldering.

4 Design

4.1 Code

- 1. Set PORTA pins RA0, RA1, RA4, RA5 as output.
- 2. Set PORTC pins RC0 and RC1 to input (AN4 and AN5 = 1).
- 3. Set up AN4 and AN5 as analog inputs using ANSEL.
- 4. Set the internal clock (ADCON1 = 00110000).
- 5. Set ADCON0.
 - (a) The ADRES value should be left-justified.
 - (b) The voltage reference should be the VDD pin.
 - (c) The analog channel should initially be set to AN5. d. The ${\rm GO/DONE}$ bit should be cleared.
 - (d) Enable the ADC.


Refer to page 70 of the PIC16F684 Data Sheet for more information on how to configure these registers.

- 6. Begin the main program loop.
- 7. Save the ADRESH value.
- 8. Set the analog channel to AN4 and repeat the procedure for the other sensor. 9. Compare the ADRES values to a threshold value.

9. If the sensor sees white, turn the corresponding wheel, else stop the motor. 11. Repeat program indefinitely to continue reading sensors.

Refer to the attached document for the specific code used.

4.2 Program Flowchart



4.3 Circuit

- 1. Build the motor controller circuit on the breadboard that came preattached with the robot chassis. Refer to appropriate datasheet and pictures in the appendix for more information.
- 2. Connect both motors to the motor controller.
- 3. On a different breadboard, construct the sensor circuitry. Use appropriate 10K and 320 resistors to avoid damage to the sensors. Refer to datasheet for detailed information regarding the use of correct resistors as to not damage the sensor.
- 4. Ensure the use of a voltage regulator connected to both the motor controller circuit and the sensor circuitry.
- 5. Connect an external power supply to power all the components PIC microcontroller, sensors and L293DNE with 5V through the voltage regulator.

6. Connect the ground of all components - PIC microcontroller, sensors and L293DNE - to the ground of the power supply.

Refer to the attached document for a full schematic of the motor controller circuit. The sensor circuit has been omitted as it was not used in the final design of the robot.

4.4 Hardware

- 1. Using screws and brackets, attach the sensors 3.5 cm apart in width to allow it to straddle the line which is approximately 2 cm in width. This gives the robot approximately 0.75 cm on each side of the line to detect the white surface.
- 2. Ensure they are approximately 2 mm above the ground to receive accurate readings from the sensors.
- 3. Mount the sensors 1mm in front of the robot in order to ensure easy accessibility to the sensor wiring for debugging.
- 4. Mount the breadboard containing the sensors circuitry onto the PIC microcontroller, as shown in pictures found in the appendix, using double sided tape. Then mount the entire PIC microcontroller and breadboard assembly on the top of the robot chassis with tape.

5 Problem Diagnosis and Correction

Problem Description	Symptoms	Solutions & Design Changes
The robot only moved for 2	The wheels on the robot	Solution: The solution was to provide more
seconds before coming to a	moved for 2 seconds and	voltage through an AC/DC Wall Adapter.
stop. The root cause of this	then halted to a stop. How-	Design Changes: A LM7805 voltage regula-
problem was improper cir-	ever, the motors continued	tor was added to the circuit in order to ensure
cuitry design which didn't	to turn as the sound of	that only 5V from the power source were ap-
provide any external power	the motor was clearly au-	plied to the L293DNE motor controller. This
to the L293DNE motor con-	dible. Although it is not	change was verified to be extremely effective as
troller.	known with certainty, the	it solved the problem and ensured safe opera-
	worm gear may have been	tion.
	stripped as a result.	
The left side of the robot	The incorrect spacing be-	Solution: The drive gear was pushed upwards
wouldnt move even though	tween the gears did not al-	so that it was interlocked with the worm gear
the motor was spinning as it	low for the motor to transfer	on the motor.
was audible. The root cause	torque to the wheel. Thus,	Design Changes: A screw was added to the
of this was that the worm	the robot spun in circles	bottom floor of the chassis to push the gear up-
gear of the motor was not	since only the right side	wards. This solution was extremely effective as
aligned with the drive gear	wheels were spinning.	it solved the problem and in turn, allowed for
due to incorrect spacing be-		the code to work effectively as the robot contin-
tween the two gears.		ued to move as expected.
The sensors had no impact	Due to the code not en-	Solution: Originally, it was thought the sen-
on the robots decision mak-	abling the GO/DONE bit	sors were faulty. They were replaced but de-
ing. The root cause of this	which caused the sensors t	spite not having any effect and the code having
issue is the erroneous code	never be read, the robot	been checked by several peers, the origin of the
in which the GO/DONE bit	continued to go straight off	problem could not be resolved. The issue was
was not enabled in the ADC	the track as if the sensors	only noticed after an example code was shown
procedure. As such, the	were always seeing white.	by Mr. Balcita on the sue of ADC conversion.
analog signal from the sen-		Design Changes The robot was changed to
sors were never being read		use timed delays to hardcode its decision mak-
as digital.		ing process so that it would follow the preset
		track. Although extremely effective and quick,
		this design could have been avoided by being
		persistent with the light sensors.

6 Conclusion

The original objective was to construct a line following robot using the assembly language to program the PIC 16F684 microcontroller. The specifications indicated using light sensors to sense a black line on a white surface that will allow the robot to complete one lap of the track made out of black electrical tape in 60 seconds.

The robot does not meet the original objective as it is able to move around the track but not complete a full lap on the track. Additionally, the robot uses a hardcoded assembly program instead of using light sensors to follow the line.

7 Appendix




Figure 1: The final robot layout is shown to the left. The motor controller circuit is mounted beneath the PIC16F684 Microcontroller.




Figure 2: The circuit diagram shown above does not include the circuit for the QRD1114 light sensors.

7.1 Final Code

Please refer to document within the main directory of this report for .txt code file.