
Charge only
Both calibrated
Separate axial gains
Shared axial gain
Two fields; baseline
(a)
Three q values
Some input meshes fail
(b)
Three μ values
Some input meshes fail
(c)
Relative L2 RMS (%)
10^2
10^1
10^0
10^{-1}
10^{-2}
0
0 4 8 12 16 20 24
Trial U_a (t)