<u>ITEM</u>	<u>QTY</u>	DESCRIPTION	PART NUMBER
1 2 3 4 5	1 1 1 1	TOP BODY ASSEMBLY BOTTOM BODY MOTOR ASSEMBLY STRIKER ASSEMBLY PROBE ASSEMBLY	SEE CHARTII U-441 SEE CHART I A-242 A-226
+ 6 7 8 9 10	1 1 1 1	CELL OVERFLOW TUBE STRAINER SCREEN FLUSH PLUG FITTING	T-263 U-445 T-267 U-472 T-266
11 12 × + 13 14 ◊ × + 15	1 1 1 PKG 1 2	FLOW TUBE ASSEMBLY TUBING CLEANING BALLS STARWHEEL ASSEMBLY O RING	A-228 U-488 R-371 BM-709 OB-11-011
	3 2 2 4 4	O RING O RING GASKET 1/4-20 X 2-3/4 INCH LG RD HD SCREW 10-24 X 1 INCH LG FILL HD SCREW	OB-11-128 OB-11-013 G-130 N-125 N-126
21 22 23 24 25	2 3 1 1	6-32 X 1/4 INCH LG TR HD SCREW 8/32 X 3/8 INCH LG RD HD SCREW 10-32 X –1/2 INCH LG SKT SET SCREW 10-32 SKT SCREW ADAPTOR	N-127 N-169 N-170 SEE CHART 1 U-470
26 27 28	4 1 1	10-24 X 1/2 INCH LG FILL HD SCREW SEAL CELL WIRE HARNESS	N-138 U-1594 A-1092

CHART I

			VOLTAGES		
KEY	SERIES 870 / 1874			SERIES 1870	
NO.	100 VAC 50HZ	120 VAC 60HZ	240 VAC 50HZ	120 VAC 60HZ	120 VAC 60HZ
3	A-572	BM-1066-1	BM-1066-2	A-1088	A-1089
24	N-225	N345	N-345	N-345	N-345

CHART II

KEY NO.	CABINET MOUNTED	PANEL MOUNTED	
1	A-1030	A-232	

NOTES

- 1. ITEMS MARKED + ARE INCLUDED IN SERVICE KIT SK-205 YEARLY SERVICE KIT FOR CELL WITH BUFFER BOTTLE.
- 2. ITEMS MARKED × ARE INCLUDED IN SERVICE KIT SK-205-A YEARLY SERVICE KIT FOR CELL WITH BUFFER PUMP (PUMP NOT SHOWN)
- 3. ITEMS MARKED ◊ ARE INCLUDED IN SERVICE KIT SK-105-B QUARTERLY SERVICE KIT

