Gasket Quality Review Procedure

Document ID: Q-GASKET-01 | Product: P-GASKET02 | Revision: 1.0

Issued: October 1, 2026 | Publisher: Blessed IT Solution Pvt Ltd

Fictional quality procedure for the hackathon only. It is not an operating instruction for a real factory.

Purpose and strict product scope

This procedure covers the fictional Demonstration sealing gasket, product P-GASKET02. It does not apply to P-PLATE01 metal plates. Do not use these instructions for the plate inspection workflow, even if a question mentions a defect or quality review.

Gasket specific record

For a gasket quality concern, record the gasket inspection reference, seal-kit identifier if provided, and the packaging label. Keep these gasket-specific fields separate from other product records. An absent seal-kit identifier is recorded as Not provided.

Gasket evidence request

Request a view of the gasket circumference and packaging label for a manual quality review. This request concerns a sealing component and must not be transferred to metal plates. The procedure provides no numerical sealing tolerance or image classifier.

Demonstration scope

The Round 2 plate classifier does not inspect gaskets. This document exists as a separate reference in the demonstration corpus. Its presence does not authorize using plate predictions as gasket results or changing a saved inspection product.

Gasket Review and Limits

Review routing

Send the gasket record to a Supervisor for manual review. Preserve the source image, any supplied packaging label, and the original observations. A review request does not authorize installation, repair, or shipment.

Missing information

When the gasket image or packaging evidence is unavailable, record the gap and request the missing evidence. Do not guess seal material, dimensions, pressure rating, supplier, replacement interval, or compatibility with another machine.

Source isolation

Q-GASKET-01 revision 1.0 is associated only with P-GASKET02. It is neither an alternative revision nor a fallback for Q-PLATE-01 or Q-PLATE-02. A missing plate reference must remain a missing-evidence condition for the plate workflow.