Plate Quality Containment Procedure

Document ID: Q-PLATE-01 | Product: P-PLATE01 | Revision: 1.0

Issued: October 1, 2026 | Publisher: Blessed IT Solution Pvt Ltd

Fictional quality procedure for the hackathon only. It is not an operating instruction for a real factory.

Purpose and scope

This procedure applies only to the Demonstration metal plate, product P-PLATE01. It defines the initial documented response to a completed inspection with an original Defective model prediction. Use Q-PLATE-02 revision 1.0 for evidence review and approval. Both procedures apply.

Initial handling

Create a quality incident linked to the saved inspection. Record the product ID, inspection ID, submitting user, inspection timestamp, original predicted class, confidence, and model version. Preserve the original image and any existing human review.

Record a proposed quality hold for the inspected item pending Supervisor review. The portal records this proposed disposition only; it does not move stock or apply controls to equipment. Keep the image linked to the incident so the reviewer can compare it with the prediction.

Scope of containment

Containment in this demonstration covers the inspected item only. The image and classifier output do not establish a batch-wide defect. Do not recommend disposal of an entire batch, shutdown of a production line, or changes to equipment settings.

If a batch or lot reference is already available, include it in the record. If absent, record Not provided. Do not invent a batch number or block the incident merely because this optional field is absent.

Evidence Collection and Escalation

Evidence to preserve

Keep the original image reference, original model output, confidence, model version, and any human correction available side by side. A human correction must not erase the model prediction. Link all proposed actions to this incident and the relevant procedure page.

Next steps for the inspected item

Request a Supervisor review of the image, inspection record, and applicable procedures. Summarize the item as flagged by the classifier; do not describe it as a confirmed physical defect unless separately supported by a recorded human observation.

For incomplete or unsuitable visual evidence, request a clearer inspection image through the normal inspection workflow and retain a link to the original record. A new image creates a separate inspection; it does not replace the earlier model output.

Boundaries of the evidence

The supplied binary classifier does not identify scratches versus pits, defect dimensions, material strength, root cause, or the cost of rework. Do not infer these facts from its Defective label. This procedure supplies no repair recipe, grinding depth, acceptance tolerance, scrap rule, or supplier instruction.

Handoff

Pass the incident, image reference, source citations, and evidence gaps to the Supervisor under Q-PLATE-02. A proposed hold and an AI-generated action list are not authorization to rework, scrap, or release the item.