
## **Experiment 33**

## **Hanning window Low Pass Filter**

Plot magnitude response and phase response of Low Pass filter with desired parameters using Hanning window

```
clc;
clear all;
close all;

N = 10;
wc = 0.6*pi;  % cutoff frequency
h = fir1(N,wc/pi,hanning(N+1));
freqz(h);
```



## **Conclusion**

The required filter was successfully obtained using rectangular window. Its magnitude and phse plot are displayed.

Published with MATLAB® R2013a